

Filter Replacement - Hyundai 1500 / 600 / 330

Step 1

Turn off power at the wall and remove the plug

Step 2

Turn off tap at the wall

Step 3

Gently undo the hose from the filter

Step 4

Turn the filter counter clockwise and dispose in the recycling bin
Simply reverse the procedure to replace the new filter

For optimal performance of your Hyundai Bidet, the filter should be changed every 6-12 months.

Freecall 1800 BIDETSHOP, that's 1800 243 387

**The
BIDET
SHOP**